



Product: V273 ANSI II Surveyor Safety Vest

HOW TO MEASURE



CHEST MEASUREMENT

On a person, measure just under the arms, across fullest part of chest, around entire body holding tape firm and level

BODY WIDTH

Lay garment flat 1 Inch below the armhole flat measure the garment across the chest.

BODY LENGTH

Lay garment flat (face down) Measure from center back neckline seam straight down to bottom of the front hem.

SIZE CHART

| | S | M | L | XL | 2XL | 3XL | 4XL | 5XL |
|--------------------------|--------|--------|--------|--------|--------|--------|--------|--------|
| CHEST MEASUREMENT | 21 | 22-1/2 | 24 | 25-1/2 | 27 | 28-1/2 | 30 | 31-1/2 |
| BODY WIDTH | 22-1/2 | 23 | 24 | 25-1/2 | 27 | 28-1/2 | 30 | 31-1/2 |
| BODY LENGTH | 30-1/4 | 28-1/4 | 28-1/4 | 28-1/2 | 28-1/2 | 28-3/4 | 28-3/4 | 29 |

| Technical Data | |
|----------------------------|---------------------------------------|
| Material | Polyester |
| Main Fabric | 110 Grams/Square Meter |
| Reflective Material | 2" Silver Reflective Material Level 2 |
| Ansi-107-2015 Class | ANSI Class 2 |
| Color(s) | Lime & Orange |
| Size Range | Small - 5XLarge |



R & R INDUSTRIES, INC.
1-800-234-5611

ANSI/ISEA 107-2015

STYLE# V273
SIZE:



Type R
Class 2
Not FR

This garment is not flame resistant
as defined by ANSI/ISEA 107-2015
Section 10.5.

RN# 73907

CARE INSTRUCTIONS

HAND WASH COLD
NO BLEACH, HANG TO DRY
DO NOT IRON, DO NOT DRY CLEAN
100% POLYESTER



MAX 25 WASHES

This garment is not designed to protect against severe heat/flame or hazardous materials. Do not wear garments with less visibility protection over this one. Periodic comparison to new garments are recommended to assure effectiveness. Do not store wet or exposed to sunlight.

MADE IN CHINA