



Product: PE320 ANSI Class E Industrial Work Rainwear Bib Pant

HOW TO MEASURE



CHEST MEASUREMENT

On a person, measure just under the arms, across fullest part of chest, around entire body holding tape firm and level

BODY WIDTH

Lay garment flat 1 Inch below the armhole flat measure the garment across the chest.

BODY LENGTH

Lay garment flat (face down) Measure from center back neckline seam straight down to bottom of the front hem.

SIZE CHART

	M	L	XL	2XL	3XL	4XL
CHEST MEASUREMENT	47 ½	49	50	51	52	53
BODY WIDTH	43 ¼	43 ¾	44 ¼	44 ¾	45 ¼	45 ¼
BODY LENGTH	29.375	29.375	29 ½	29 ½	29 ¼	29 ¼

SPECIAL FEATURES

- Waterproof polyester, breathable, mildew resistant
- Maximum freedom of movement
- Stitched and tape sealed seams for 100% waterproof protection
- Suspenders w/quick release buckles & crossover non-conductive, non-corrosive hardware
- 2" silver reflective material stripes